

March 2021

Tel 604.792.1321 | Fax 604.792.9665 | <http://www.sd33.bc.ca/>



Stitó:s Lá:lém totí:lt Update

- Stairs to 2nd floor



- Steel stud framing in main hall
- Framing in classroom



- Forms being craned in for concrete support columns
- Roof trusses on 2nd floor



- Roof trusses being installed on 2nd floor
- Shop in front and small gym behind




- Roof framing over second floor classrooms
- Gym roof insulation preparing for install



- Prep work for learning commons 2-story push out area



- Interior wall install and insulation
- Ongoing HVAC and electrical installation



- Steel supports and beams for roof being installed
- Roof decking going on 2nd floor classrooms

