

April 2021

Tel 604.792.1321 | Fax 604.792.9665 | <http://www.sd33.bc.ca/>



Stitó:s Lá:lém totí:lt Update

- Steel stud framing for exterior windows on first floor




- Lower floor of Learning Commons, bottom of sit/stand stairs. Adds a great presentation space!
- Roofing work



- Roofing work including second floor structural steel



- Parapet walls and classroom window and door framing on second floor
- Interior steel stud work on 1st floor including gyms



- HVAC, plumbing, electrical and sprinkler work
- Insulation of heating duct and piping
- Second floor HVAC for classrooms



- Forming and foundation work for field house (change rooms and storage)



- Weatherproofing on exterior

