

September 2021

Tel 604.792.1321 | Fax 604.792.9665 | <http://www.sd33.bc.ca/>



Stitó:s Lá:lém totí:lt Update

- Installation of interior railings
- Roof top mechanical ventilators arrived for install





- Landing the mechanical units
- Installation of HVAC roof top units



- Installation of drywall on the ground floor



- Installation of drywall on the ground floor continued
- Framing exterior windows



- Centre main hallway looking up to second floor



- Second floor main hallway
- Learning Commons looking up from bottom
- Learning Commons second floor looking straight out towards river

